



Power Restored at West Anaheim Street

Damaged electric lines have been repaired

May 22, 2014

Power has been restored to the businesses surrounding the West Anaheim Street construction area. A crane accidentally struck a power line around 10 p.m. Wednesday night which caused the area to lose power.

The crane was involved in a Port project to improve Anaheim Street, which is the northern boundary of the harbor district. In addition to roadway resurfacing, the project includes improvements for sidewalks, bus stops, median, access for the disabled and landscaping.

For more information, see our website at www.polb.com/anaheimstreet. Or contact the Port at anaheimstreet@polb.com or (562) 283-7715.

Follow the Port of Long Beach:

 [Facebook](#)

 [@portoflongbeach](#)

 [YouTube](#)

 [polb.com](#)